



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER JOHN R. BAZA
Executive Director Division Director

Inspection Report
Minerals Regulatory Program
August 19, 2009

Reviewed: LK

Mine Name: Dry Wash	Permit Number: S/015/0096
Operator Name: Miracle Rock Mining	Inspection Date: June 23, 2009
Inspector(s): Wayne Western	Time: 2:20 – 2:45 pm
Other Participants: none	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount:

The surety is for \$23,000.00.

Permit fee:

July 1, 2008, - \$150.00

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The Permittee pocked some areas on the north side. Vegetation was established in those pocks see pictures. The Permittee pocked some areas on the south side. Some of the vegetation might be halogeton and should be controlled in order for the sight to be eligible for bond release.

Directions:

Go to Cleveland then head north toward Elmo turn east on County Road 211 (1/2 mile past Cleveland) go past Deseret Waterfowl Management Area and head towards Cleveland Lloyd Dinosaur Quarry. Mine is visible from the road.

Conclusions and Recommendations:

The Permittee appears to comply with the mineral rules.

Inspector's Signature

Wayne Watson 8/19/2009

WHW:

cc: Dave Taylor, Miracle Rock

O:\M015-Emery\S0150096-DryWash\draft\insp_06232009A.doc



North pit



Overburden



Pocking



Pocking